



WS1

Universal Inductive Cradle
AC118




1

Place cradle onto stand (AC110).




2

Use TT-20 bit to screw cradle to stand.




3a

Optional: Slide sensor landing pad into cradle.




3b

Use TT-20 bit to screw sensor landing pad to cradle.



4

Note: Watch should be centered on circle of cradle.



SD0313 Rev0 12/22/15

inVue®

www.invue.com

NA / LATAM // 704.752.6513 • 888.55.INVUE

EMEA // +31.23.8900150

APAC // +852.3127.6811