



WS1


LG G Watch R / Urbane Sensor
AC180




- 1 Remove top band (with clasp) from watch using clawed end of sensor installation tool (AC196) to grip watch pin.




- 2 Insert pin of sensor into holes of watch head as shown. Confirm charging contact is on same side as sensor and completely depress plunger in sensor with watch body.



- 3 Insert pin of watch band into sensor using flat end of sensor installation tool.



- 4 Place sensor into cradle (AC181) and firmly plug sensor into stand.



SD0296 Rev0 08/25/15

inVue®

www.invuesecurity.com

NA / LATAM // 704.752.6513 • 888.55.INVUE

EMEA // +31.23.8900150

APAC // +852.3127.6811