


CT200


Stand Adhesive
ADH2101




- 1 Remove 4 rubber feet from base of stand.




- 2 Wipe 4 recessed, triangular surfaces with alcohol wipe provided. Also wipe the surface of the counter where the stand will be. Let surfaces dry.





- 3 Apply 4 adhesive pads to the 4 recessed triangular surfaces.




- 4 Ensure cables are routed out the back of the stand and that they are laying in the channel in the bottom of the stand.



- 5 Remove the release liners from the 4 adhesive pads. Place the stand into position on the counter and press down on it for 10 seconds.



- 6 Use removal tool CTG2P002 to remove the stand from the counter.



SD0397 Rev0 09/27/16

INVUE®

www.invue.com

NA / LATAM // 704.752.6513 • 888.55.INVUE

EMEA // +31.23.8900150

APAC // +852.3127.6811